


NCi-6 non-contact tool setting interface



Compliance information for this product is available by scanning the QR code or visiting www.renishaw.com/mtpdoc



Contents

| | |
|---|-----|
| Before you begin | 1-1 |
| Warranty | 1-1 |
| CNC machines | 1-1 |
| Care of the interface | 1-1 |
| Patents | 1-1 |
| Intended use | 1-1 |
| Safety | 1-2 |
| Information to the machine supplier/ installer | 1-2 |
| Information to the equipment installer | 1-2 |
| Equipment operation | 1-2 |
| WARNINGS | 1-2 |
| Specification | 1-3 |
| NCi-6 basics | 2-1 |
| Introduction | 2-1 |
| Power supply | 2-1 |
| Input / output over-current protection | 2-1 |
| NCi-6 interface unit (top face) | 2-2 |
| NCi-6 interface unit (bottom face) | 2-2 |
| NCi-6 top label | 2-3 |
| NCi-6 bottom label | 2-3 |
| Connectors CN1 and CN2 | 2-4 |
| Interface LEDs | 2-5 |
| Interface LED states | 2-5 |
| Status LED | 2-5 |
| Pulse width LED | 2-5 |
| Auxiliary relay status LED | 2-5 |
| Mode LEDs: (Tool set 1, Tool break, Latch and Tool set 2) | 2-5 |
| Interface LEDs – status LED | 2-6 |
| Switches | 2-7 |
| Switch locations | 2-7 |
| IMPORTANT: Setting a switch. | 2-8 |
| Switch bank SW1 | 2-8 |
| Switch bank SW2 | 2-8 |
| Switch bank SW3 | 2-9 |
| SSR2 output selections | 2-9 |
| SSR2 type 1 and SSR2 type 2 | 2-9 |

| | |
|--|-----|
| System installation | 3-1 |
| Operating modes | 3-1 |
| Tool set mode 1 | 3-1 |
| Tool set mode 2 | 3-1 |
| High-speed tool breakage detection | 3-1 |
| Latch mode | 3-1 |
| Mode selection | 3-1 |
| Pulse width setting | 3-2 |
| Tool set mode 1 (without drip rejection) | 3-2 |
| Tool set mode 1 (with drip rejection) | 3-3 |
| Tool set mode 2 | 3-3 |
| Dimensions and mounting arrangements | 3-4 |
| Wiring | 3-5 |
| Connecting to the NC unit | 3-5 |
| Connecting to the CNC | 3-6 |
| Controlling the laser of an NC unit | 3-7 |
| Sharing the skip with an auxiliary probe | 3-8 |
| Controlling the air supply to an NC unit | 3-9 |
| Maintenance | 4-1 |
| NCi-6 maintenance | 4-1 |
| Parts list | 5-1 |

Before you begin

Warranty

Unless you and Renishaw have agreed and signed a separate written agreement, the equipment and/or software are sold subject to the Renishaw Standard Terms and Conditions supplied with such equipment and/or software, or available on request from your local Renishaw office.

Renishaw warrants its equipment and software for a limited period (as set out in the Standard Terms and Conditions), provided that they are installed and used exactly as defined in associated Renishaw documentation. You should consult these Standard Terms and Conditions to find out the full details of your warranty.

Equipment and/or software purchased by you from a third-party supplier is subject to separate terms and conditions supplied with such equipment and/or software. You should contact your third-party supplier for details.

CNC machines

CNC machine tools must always be operated by fully trained personnel in accordance with the manufacturer's instructions.

Care of the interface

Keep system components clean.

Patents

Features of the NCI-6 non-contact interface and related products are subject to the following patents and patent applications:

CN 100394139
EP 1502699
EP 2152469
JP 4520240
US 7312433
US 9040899

Intended use

The NCI-6 non-contact tool setting interface is used in conjunction with NC4, NC4+ or NC4+ Blue non contact tool setters. The NCI-6 unit converts signals from the non-contact tool setter into voltage-free, solid-state relay (SSR) outputs for transmission to the CNC machine control.

Safety

In all applications involving the use of machine tools or CMMs, eye protection is recommended.

Information to the machine supplier/ installer

It is the machine supplier's responsibility to ensure that the user is made aware of any hazards involved in operation, including those mentioned in Renishaw product literature, and to ensure that adequate guards and safety interlocks are provided.

Under certain circumstances, the probe signal may falsely indicate a probe seated condition. Do not rely on probe signals to halt the movement of the machine.

Information to the equipment installer

All Renishaw equipment is designed to comply with the relevant UK, EU and FCC regulatory requirements. It is the responsibility of the equipment installer to ensure that the following guidelines are adhered to, in order for the product to function in accordance with these regulations:

- any interface MUST be installed in a position away from any potential sources of electrical noise, i.e. power transformers, servo drives etc.;
- all 0 V/ground connections should be connected to the machine "star point" (the "star point" is a single point return for all equipment ground and screen cables). This is very important and failure to adhere to this can cause a potential difference between grounds;
- all screens must be connected as outlined in the user instructions;
- cables must not be routed alongside high current sources, i.e. motor power supply cables etc., or be near high-speed data lines;
- cable lengths should always be kept to a minimum.

Equipment operation

If this equipment is used in a manner not specified by the manufacturer, the protection provided by the equipment may be impaired.

WARNINGS

Use of controls or adjustments or performance of procedures other than those specified within this publication may result in hazardous radiation exposure.

Switch off electrical power to the NCi-6 interface before carrying out maintenance on non-contact (NC) tool setting and tool breakage detection products.



CAUTION – LASER SAFETY

The NCi-6 interfaces with Renishaw laser-based non-contact tool setting and tool breakage detection products. Laser safety guidelines and safety rules are described in the appropriate NC tool setting product guides.

If the equipment is used in a manner not specified by the manufacturer, the protection provided by the equipment may be impaired.

Specification

| | |
|---|---|
| Absolute maximum supply voltage | 11 Vdc to 30 Vdc |
| Maximum rated current | 0.5 A |
| SSR contact ratings | ±50 mA pk ±30 Vdc pk |
| Protection provided by enclosure | IP20 BS EN 60529:1992+A2:2013 |
| Altitude | Maximum 2000 m (6562 ft) |
| Operating temperature | +5 °C to +55 °C (+41 °F to +131 °F) |
| Storage temperature | -25 °C to +70 °C (-13 °F to +158 °F) |
| Relative humidity | Maximum relative humidity 80% for temperatures up to +31 °C (+87.8 °F) decreasing linearly to 50% relative humidity at +40 °C (104 °F). |

This page is intentionally left blank.

NCi-6 basics

Introduction

CNC machine tools using Renishaw NC4, NC4+ or NC4+ Blue non-contact (NC) units for tool setting or broken tool detection require an interface unit. The NCI-6 unit converts signals from the NC unit into voltage-free, solid-state relay (SSR) outputs for transmission to the CNC machine control.

The NCI-6 interface unit should be installed in the CNC control cabinet. Where possible, site the unit away from potential sources of interference such as transformers and motor controllers.

CAUTION: Only qualified persons should install and adjust switches on the interface. Remove the DC power supply from the NCI-6 unit before removing the cover.

Power supply

The NCI-6 interface can draw its power from the CNC machine's nominal 12 Vdc to 24 Vdc supply. This must be an appropriate single fault tolerant power supply which must comply to BS EN IEC 62368-1.

The supply to the NCI-6 is protected by a 0.5 A resettable fuse. To reset the fuse, remove the power then identify and rectify the cause of the fault.

The nominal current when connected to an NC unit is as follows:

120 mA @ 12 Vdc,
70 mA @ 24 Vdc

NOTE: To disconnect the power supply, remove the wires from the terminals.


Input / output over-current protection

Each of the SSR outputs is protected by a 50 mA resettable fuse.


The auxiliary relay output is protected by a 200 mA resettable fuse.

The NC unit is protected by a resettable current protection circuit.

NCi-6 interface unit (top face)



NCi-6 interface unit (bottom face)



NCi-6 top label

| | | | |
|----|-----------------|-----|-------|
| ±4 | SSR2 Type 2 | Osc | SW2-3 |
| 3 | Not Used | - | - |
| 2 | M-code 2 Active | Low | High |
| 1 | M-code 1 Active | Low | High |
| | SW3 (inside) | On | Off |

| | | | |
|----|-------------------|-------|-------|
| ±4 | Pulse Width (ms) | 20 | 100 |
| ±3 | SSR2 Type 1 Level | Pulse | Pulse |
| 2 | SSR2 State | N/C | N/O |
| 1 | SSR1 State | N/C | N/O |
| | SW2 (inside) | On | Off |

| | | | | | |
|----|-----|---|---|---|---|
| ON | OFF | 1 | 2 | 3 | 4 |
| ON | OFF | 1 | 2 | 3 | 4 |

| | | | | | |
|----|-----|---|---|---|---|
| ON | OFF | 1 | 2 | 3 | 4 |
| ON | OFF | 1 | 2 | 3 | 4 |

RENISHAW

NCi-6
Part No A-6516-2000

CE

Patents Applied For

| Pin | NC4 Conns | Setup DVM | Auxiliary 11-30Vdc | White | Purple | Blue | Black | Red | Screen | Grey |
|-----|-----------|-----------|--------------------|-------|--------|------|-------|-----|--------|------|
| 1 | | | | | | | | | | |
| 2 | | | | | | | | | | |
| 3 | | | | | | | | | | |
| 4 | | | | | | | | | | |
| 5 | | | | | | | | | | |
| 6 | | | | | | | | | | |
| 7 | | | | | | | | | | |
| 8 | | | | | | | | | | |
| 9 | | | | | | | | | | |
| 10 | | | | | | | | | | |

| SW1 (Front) | 1 | 2 | 3 | 4 |
|----------------|-----|------|---|---|
| Not Used | 1 | 2 | 3 | 4 |
| NC Set-Up | 1 | 2 | 3 | 4 |
| Drip Rejection | 1 | 2 | 3 | 4 |
| Drip Rej RPM | 1 | 2 | 3 | 4 |
| | 500 | 1000 | | |

*For M-code settings see label on reverse.

†For use of switch with M-code 3 see label on reverse.

‡SW2-3 & SW3-4 set the SSR2 output type. Refer to user guide for information.

PULSE WIDTH 20

STATUS

AUX. RELAY STATUS

NCi-6

TOOL SET MODE 1

TOOL BREAK MODE

LATCH MODE

TOOL SET MODE 2

NCi-6 bottom label

RENISHAW

NCi-6
Part No A-6516-2000

| Mode Settings | | |
|---------------|----------|----------|
| Mode | M-code 1 | M-code 2 |
| Tool Set 1 | Inactive | Inactive |
| Tool Set 2 | Active | Active |
| Tool Break | Active | Inactive |
| Latch | Inactive | Active |

| M-code 3 Pulse Width Settings | | | |
|-------------------------------|------------------|------------|----------|
| Min RPM | Pulse Width (ms) | Switch 2-4 | M-code 3 |
| 600 | 100 | Off | Low |
| | | On | High |
| 3000 | 20 | On | Low |
| | | Off | High |

See user guide for more information.

Scan code for more information.

Connectors CN1 and CN2

10-way connector (CN1)

Connector CN1 is used to connect the non-contact unit to the NCI-6 interface.

Terminals 1 – 2

Used to monitor the signal from the NC unit. Voltage range: 0 Vdc to 9 Vdc.

15-way connector (CN2)

Connector CN2 is used to connect the NCI-6 interface to the CNC machine tool.

Terminal 1

Used to select the pulse width in consideration with switch SW2-4.

Terminals 3 – 6

This is an auxiliary output that can be used to control external devices such as LED, a buzzer or an air blast.

This output can also be used with a hardwired NC unit to switch the transmitter unit on/off independently of the receiver.

Alternatively, it can act as a skip-sharing module to switch between a non-contact tool setting device and an interface for spindle probing.

This output is fused at 200 mA.

Terminals 7 – 8

This is an SSR output that can be configured to be either normally open (N.O.) or normally closed (N.C.). The output is fused at 50 mA.

Terminals 9 – 10

This is an SSR output that can be configured to be either normally open (N.O.) or normally closed (N.C.), as well as providing a pulsed, level or oscillating output. The output is fused at 50 mA.

Terminals 11 – 12

This is used to select the operating mode.

Terminals 13 – 15

This is used to supply power to the interface.

Interface LEDs

Interface LED states

Seven LEDs are fitted on the front of the NCI-6 interface. These provide the operator with a visual indication of the system's status.



Status LED

The Status LED indicates the status of the NC system to the operator. The colours and associated states are described in the tables on page 2-6.

When the system is in set-up mode, the LED changes from red to amber to green as the beam voltage increases.

If the LED is green after exiting set-up mode, this indicates that set-up has been successful. If the LED is not green, this indicates that set-up has not been successful and must be repeated.

Pulse width LED

| | | | |
|---------------|------|-----------------|-------|
| Green: | 20ms | Not lit: | 100ms |
|---------------|------|-----------------|-------|

Auxiliary relay status LED

| | | | |
|---------------|---------------------------|-----------------|-------------------------------|
| Green: | Auxiliary relay energised | Not lit: | Auxiliary relay not energised |
|---------------|---------------------------|-----------------|-------------------------------|

Mode LEDs: (Tool set 1, Tool break, Latch and Tool set 2)

| | | | |
|---------------|---------------|-----------------|-------------------|
| Green: | Mode selected | Not lit: | Mode not selected |
|---------------|---------------|-----------------|-------------------|

For more information see chapter 3, "System installation".

NOTE: If no mode LEDs are lit, this indicates that the NCI-6 interface is in set-up mode.

Interface LEDs – status LED

| LED colour | Tool set mode 1 | Tool set mode 2 |
|-------------|--|--|
| Green/amber | Flashing at 1 Hz. The system operating voltage is too high. The system will continue to function, but for optimum performance repeat the set-up and alignment procedures. The probe is untriggered. | Flashing at 1 Hz. The system operating voltage is too high. The system will continue to function, but for optimum performance repeat the set-up and alignment procedures. The probe is triggered. |
| Green | The beam is clear. The probe is untriggered. | The beam is clear. The probe is triggered. |
| Amber | The beam is partially blocked. * The probe is untriggered. | The beam is partially blocked. * The probe is triggered. |
| Red | The beam is blocked. The probe is triggered. | The beam is blocked. The probe is untriggered. |
| No light | No power to the unit | |

* If the laser beam is clear and the LED is amber, this indicates that the system will continue to function, but for optimum performance maintenance is required.

Refer to the applicable *installation and user's guide* (for *NC4*, Renishaw part number H-2000-5230 or *NC4+*, Renishaw part number H-6270-8501 or *NC4+ Blue*, Renishaw part number H-6435-8501), for details of the possible actions required.



| LED colour | High speed broken tool detection mode | Latch mode |
|-------------|--|---|
| Green/amber | Not applicable. | Flashing at 1 Hz. The output is not latched. The system operating voltage is too high. The system will continue to function, but for optimum performance repeat the set-up and alignment procedures. |
| Green | Not applicable. | The beam is clear. The output is not latched. |
| Amber | The output is not latched. The beam is blocked. | The output is not latched. The beam is blocked. * |
| Red | The output is latched. The tool is broken. | The output is latched. |
| No light | | |

* If the laser beam is clear and the LED is amber, this indicates that the system will continue to function, but for optimum performance maintenance is required.

Refer to the applicable *installation and user's guide* (for *NC4*, Renishaw part number H-2000-5230 or *SwiNC4+*, Renishaw part number H-6270-8501 or *NC4+ Blue*, Renishaw part number H-6435-8501), for details of the possible actions required.

Switches

Switch locations



IMPORTANT: Setting a switch

When setting a switch to either the On or Off position, apply firm pressure to make sure it is fully in position.

Switch bank SW1

| Switch | On | Off | | |
|--------|----------------|-----|------|--|
| 1 | Not used | On | Off | Not used. |
| 2 | NC set-up | On | Off | Used when setting up an NC unit. Set this switch to On so that the alignment voltage can be maximised. After maximising the voltage, set the switch to Off so that the automatic gain circuitry can set the operating voltage. |
| 3 | Drip rejection | On | Off | When the drip rejection mode is set to On, the effects of individual drops of coolant on measurements are filtered out. NOTE: For safe operation, set the spindle speed and spindle override as described below. |
| 4 | Spindle r/min | 500 | 1000 | Used with drip rejection. For safe operation, the spindle speed must be fixed at a whole multiple, e.g. 1000, 2000, or 3000; or 500, 1000, or 1500, and the spindle override must be disabled. |

Switch bank SW2

CAUTIONS:

With the SSR output switch(es) set to Off, i.e. normally open (N.O.), the respective output will remain in a non-triggered state if the power supply is interrupted and/or a poor connection is made to the SSR.

If using SSR2 as an oscillating or pulsed output for a trigger signal to the control, the level output SSR1 must be used to guarantee a reliable probe status check.

| Switch | On | Off | | |
|--------|-------------|-------|--------|---|
| 1 | SSR1 | N.C. | N.O. | Sets the SSR output to either normally closed (N.C.) or normally open (N.O.). |
| 2 | SSR2 | N.C. | N.O. | As above. |
| 3 | SSR2 Type1 | Level | Pulsed | Sets the SSR2 output to level or pulsed. Refer to page 2-9. |
| 4 | Pulse width | 20 ms | 100 ms | Sets the pulse width to either 20 ms or 100 ms (For more information see chapter 3, "System installation"). M-code 3 may be used to invert the switch setting. NOTE: For the cycle to work, the pulse width value selected must be the same as the value that is configured in the tool setting software. |

Switch bank SW3

| Switch | | On | Off | |
|--------|-----------------|------|----------|---|
| 1 | M-code 1 Active | Low | High | Determines whether the input responds to an active – high or active – low signal. |
| 2 | M-code 2 Active | Low | High | Determines whether the input responds to an active – high or active – low signal. |
| 3 | Not used | – | – | Not used. |
| 4 | SSR2 Type 2 | Osc. | As SW2-3 | Sets the SSR2 output to oscillating or as per SW2-3. Refer to section “SSR2 output selections”. |

NOTES:

If an M-code is not connected to terminal 11, SW3-1 must be set to Off (M-code active high).

If an M-code is not connected to terminal 12, SW3-2 must be set to Off (M-code active high).

SSR2 output selections

SSR2 type 1 and SSR2 type 2

CAUTION: If using SSR2 as an oscillating or pulsed output for a trigger signal to the control, the level output SSR1 must be used to guarantee a reliable probe status check.

The SSR2 output can be configured for three different types, pulsed, level or oscillating.

The selection of SSR2 type is derived from the position of two switches, SW2-3 and SW3-4.

The table for this logic is as follows:

| SW2-3 SSR2 Type 1 | SW3-4 SSR2 Type 2 | Output type |
|----------------------|----------------------|-------------|
| Off | Off | Pulsed |
| On | Off | Level |
| Off | On | Oscillating |
| On | On | Oscillating |

NOTE: On certain machine controllers there is a delay between the start of a measurement move and the machine controller becoming responsive to a change in trigger status. In this case use the oscillating output to ensure the trigger is detected when the machine controller becomes responsive.

This page is intentionally left blank.

System installation

Operating modes

Tool set mode 1

This mode of operation allows functions such as system alignment, tool calibration, length and diameter tool setting, and thermal compensation tracking. Measurement takes place as the tool enters the laser beam. No M-codes are required. Typically drip rejection is activated.

Tool set mode 2

This mode of operation allows length and diameter measurement of cutting tools, measures run-out and allows cutting edge checking. It uses “Dual Measurement” technology. Measurement takes place as the tool exits the laser beam providing shorter cycle times and is more robust in wet conditions. M-codes are required to activate this mode. Drip rejection is not used.

High-speed tool breakage detection

This mode of operation allows rapid detection of broken tools that are solid at the centre – for example, drills and taps.

Latch mode


This mode of operation allows functions such as checking tools for missing inserts and profile checking.

For further information about the software for these cycles, see Probe software for machine tools, Renishaw part number H-2000-2298 or the relevant Renishaw NCTS software manual for your machine tool.

Mode selection

These modes can be activated using M-codes supplying a constant voltage of between 11 Vdc and 30 Vdc connected to CN2-11 and/or CN2-12 (see the table below). These selection levels can be inverted using switches SW3-1 and SW3-2 respectively so that 0 Vdc is used to activate the mode and 11 Vdc to 30 Vdc is used to deactivate. If the M-code voltage is floating when deactivated, a resistor is required to pull up the voltage to the supply voltage (refer to the figure below).

| Mode | M-code 1 (CN2-11) | M-code 2 (CN2-12) |
|------------|----------------------|----------------------|
| Tool set 1 | Inactive | Inactive |
| Tool set 2 | Active | Active |
| Tool break | Active | Inactive |
| Latch | Inactive | Active |




Pulse width setting

The pulse width setting has the following functions:


- Sets the SSR2 pulsed output width to either 20 ms or 100 ms. It also sets the minimum pulse width of SSR1 to either 20 ms or 100 ms.
- If the pulse width is set to 20 ms, the cycle time for the latch mode functions is reduced and the spindle speed is five times faster. In certain cycles ensure the maximum r/min of the tools is not exceeded.
- Sets the minimum r/min of the tools in tool set mode 1, without drip rejection active, and in tool set mode 2.
- Switch SW2-4 sets the pulse width to 20 ms or 100 ms. M-code 3 can be used to invert the switch setting as shown in the table below.

| Min r/min | Pulse width ms | Switch 2-4 | M-code 3 |
|-----------|----------------|------------|----------|
| 600 | 100 | Off | Low |
| | | On | High |
| 3000 | 20 | On | Low |
| | | Off | High |


Tool set mode 1 (without drip rejection)





Tool set mode 1 (with drip rejection)



Tool set mode 2




Dimensions and mounting arrangements



Dimensions in mm (in)

Wiring


Connecting to the NC unit



* If the laser beam is to be switched on and off independently of the receiver, do not connect this red wire to pin 8. Connect the transmitter as shown on page 3-7.

† Do not connect screen connections if the NC unit housing is connected to the machine ground reference (i.e. $R \leq 1\Omega$).


Connecting to the CNC




CAUTION: If using SSR2 as an oscillating or pulsed output for a trigger signal to the control, the level output SSR1 must be used to guarantee a reliable probe status check.

Controlling the laser of an NC unit

This arrangement allows the transmitter of an NC unit system to be switched on and off independently of the receiver.




Sharing the skip with an auxiliary probe



* High (11 Vdc to 30 Vdc) selects the AUX probe (and may also send the start code).
 Low (0 Vdc) or floating selects the NC probe.

Controlling the air supply to an NC unit



* High (11 Vdc to 30 Vdc) switches the air on.
Low (0 Vdc) or floating switches the air off.

This page is intentionally left blank.

Maintenance

NCi-6 maintenance

No routine maintenance is required.

Remove dust from the external surfaces with a dry cloth.

This page is intentionally left blank.

Parts list

| Type | Part number | Description |
|-------------------------------|-------------|---|
| NCi-6 interface | A-6516-2000 | NCi-6 interface and box with DIN rail mounting and two terminal blocks. |
| NCi-6 terminal block (10-way) | P-CN25-1053 | 10-way socket terminal for NCi-6 interface. |
| NCi-6 terminal block (15-way) | P-CN25-0009 | 15-way socket terminal for NCi-6 interface. |

www.renishaw.com/nci-6



#renishaw



+44 (0) 01453 524524



uk@renishaw.com

© 2017–2022 Renishaw plc. All rights reserved. This document may not be copied or reproduced in whole or in part, or transferred to any other media or language by any means, without the prior written permission of Renishaw. RENISHAW® and the probe symbol are registered trade marks of Renishaw plc. Renishaw product names, designations and the mark 'apply innovation' are trade marks of Renishaw plc or its subsidiaries. Other brand, product or company names are trade marks of their respective owners.

WHILE CONSIDERABLE EFFORT WAS MADE TO VERIFY THE ACCURACY OF THIS DOCUMENT AT PUBLICATION, ALL WARRANTIES, CONDITIONS, REPRESENTATIONS AND LIABILITY, HOWSOEVER ARISING, ARE EXCLUDED TO THE EXTENT PERMITTED BY LAW. RENISHAW RESERVES THE RIGHT TO MAKE CHANGES TO THIS DOCUMENT AND TO THE EQUIPMENT, AND/OR SOFTWARE AND THE SPECIFICATION DESCRIBED HEREIN WITHOUT OBLIGATION TO PROVIDE NOTICE OF SUCH CHANGES.

Renishaw plc. Registered in England and Wales. Company no: 1106260. Registered office: New Mills, Wotton-under-Edge, Glos, GL12 8JR, UK.

Part no.: H-6516-8500-02-A

Issued: 10.2022