

# Renishaw CMM Products Division

## PRODUCT BULLETIN – PBC1049

Product:	UCC Software	Status:	Open
Title:	Service Pack for V7.1	Date:	16 <sup>th</sup> February 2007

Originator:		Distribution:	
Jeff Hall		<b>Internal</b>	✓
		<b>Subsidiaries</b>	✓
Reviewer:		<b>OEMs</b>	✓
Brian Gow		<b>Distributors</b>	✓
		<b>Retrofitters</b>	✓

### Summary:

A problem has been found in release v7.1 of our UCC software, it is a failure of the COM implementation of the Blended Move command.

We have issued a service pack (UCC Software r7.1 – Service Pack 1.exe) that fixes this problem. It is available from the same FTP site location as the v7.1 software. Press Ctrl + left mouse click on the following link to go to the site.

<http://ftp.renishaw.com/wsh5z4pk>

This command is not used in all application software packages so the problem may not be noticed, however, we do recommend this service pack is applied to avoid possible problems in the future.

If you have any questions about this bulletin please contact the author or our help line :-  
[CMMsupport@Renishaw.com](mailto:CMMsupport@Renishaw.com)