

# Renishaw CMM Products Division

## PRODUCT BULLETIN – PBC1474

Product:	PHC10-2 IEEE	Status:	Open
Title:	PHC10-2 IEEE obsolescence Notice	Date:	22nd December 2010

Originator:		Distribution:	
D Joynson		Internal	✓
Reviewer:		Subsidiaries	✓
		OEMs	✓
		Distributors	✓
B Gow		Retrofitters	✓

### Summary:

This is a notification that the PHC10-2 IEEE interface (A-1368-0101) will be **made obsolete from September 2011**. The reason for the obsolescence is that a number of key components are no longer available.

It is Renishaw's policy to support an obsolescent product, through repair, RBE, or replacement for 5 years and endeavour to support it for a further 5 years. This policy will be applied to the PHC10-2 IEEE starting September 2011.

Affected part number is:- A-1368-0101

PHC10-2 IEEE will be deleted from the next issue of the divisional price list.

If you have any questions or comments on this bulletin please visit [www.renishaw.com/cmmsupport](http://www.renishaw.com/cmmsupport) and use the "Contact" facility. This will ensure that your call is logged and processed efficiently