Renishaw plc New Mills, Wotton-under-Edge, Gloucestershire GL12 8JR United Kingdom T +44 (0) 1453 524524 F +44 (0) 1453 524901 E UK@renishaw.com www.renishaw.com



Renishaw CMM Products Division PRODUCT BULLETIN – PB1062

Product:	UCCserver™	Status:	OPEN
Title:	UCC server [™] failing to start – illegal system dll	Date:	13 th April 2007


Originator:		Distribution:	
Dave Joynson	7.11.	Internal	✓
	DIMPA	Subsidiaries	✓
Reviewer:		OEMs	✓
Brian Gow	BU	Distributors	✓
	- June	Retrofitters	✓

Summary:

Microsoft has issued a Security Update for Windows XP (KB925902) which if installed prevents the **UCCs***erver*[™] software from running. Upon starting UCCs*erver*[™] you will get **UCCserver.exe - Illegal system DLL relocation** message appear and the application fails to run.

Microsoft has recognized that they have created a problem and have posted a patch on their WEB site. The problem is something to do with the installation order of the security updates as the windows updater does not currently have the correct order embedded.

If you see the following:-



Please install the patch from the following site.

 $\underline{\text{http://www.microsoft.com/downloads/details.aspx?familyid=74AD4188-3131-429C-8FCB-F7B3B0FD3D86\&displaylang=en}$

For more information including an accurate description of the problem please visit:-

http://support.microsoft.com/kb/935448/

Page 1 of 1 PBC1062