

Renishaw CMM Products Division

PRODUCT BULLETIN – PBC1472

Product:	MIHS	Status:	Open
Title:	MIHS obsolescence	Date:	22nd December 2010

Originator:		Distribution:	
D joynson		Internal	✓
		Subsidiaries	✓
Reviewer:		OEMs	✓
B Gow		Distributors	✓
		Retrofitters	✓

Summary:

The MIH-S & MIH-SI are being made obsolete with immediate effect. The reason is a number of components have become obsolete and alternative replacements are not available.

It is Renishaw's policy to support an obsolescent product, through repair, RBE, or replacement for 5 years and endeavour to support it for a further 5 years. This policy will be applied to the MIH-S and MIH-SI.

Some of the affected part numbers are :-

- A-1373-0001 MIH-S Head Assembly
- A-1373-0002 MIH-SI Interface Assembly
- A-1373-0100 MIH-S Kit
- A-1373-0101 MIH-S Kit + MS17 shank
- A-1373-0102 MIH-S Kit + MS13 shank kit
- A-1373-0150 MIH-SI

These products will be deleted from the next issue of the divisional price list but in the interim could you please manually delete them.

If you have any questions or comments on this bulletin please visit www.renishaw.com/cmmsupport and use the "Contact" facility. This will ensure that your call is logged and processed efficiently