Renishaw plc New Mills, Wotton-under-Edge, Gloucestershire GL12 8JR United Kingdom T +44 (0) 1453 524524 F +44 (0) 1453 524901 E UK@renishaw.com www.renishaw.com



Renishaw CMM Products Division PRODUCT BULLETIN – PBC1473

Product:	PI4-2	Status:	Open
Title:	PI4-2 obsolescence Notice	Date:	22nd December 2010

Originator:	Distribution:	
D joynson	Internal	✓
	Subsidiaries	✓
Reviewer:	OEMs	✓
B Gow	Distributors	✓
	Retrofitters	✓

Summary:

This is a notification that the PI4-2 interface will be **made obsolete from September 2011**. The functionality of the PI4-2 (A-1506-0010) is available from the PI200-2 (A-1207-0050) interface.

It is Renishaw's policy to support an obsolescent product, through repair, RBE, or replacement for 5 years and endeavour to support it for a further 5 years. This policy will be applied to the PI4-2 starting September 2011.

Affected part number is :- A-1506-0010

PI4-2 will be deleted from the next issue of the divisional price list.

If you have any questions or comments on this bulletin please visit www.renishaw.com/cmmsupport and use the "Contact" facitity. This will ensure that your call is logged and processed efficiently

Page 1 of 1 PBC1473