Renishaw plc New Mills, Wotton-under-Edge, Gloucestershire GL12 8JR United Kingdom T +44 (0) 1453 524524 F +44 (0) 1453 524901 E UK@renishaw.com www.renishaw.com



Renishaw CMM Products Division PRODUCT BULLETIN – PBC1521

Product:	PI6	Status:	Open
Title:	PI6 obsolescence	Date:	20th May 2011

Originator:	Distribution:	
D Joynson	Internal	✓
	Subsidiaries	✓
Reviewer:	OEMs	✓
M Alvarez	Distributors	✓
	Retrofitters	✓

Summary:

The PI6 is being made obsolete with immediate effect. The product has become a very low volume product and a number of key components have become obsolete.

The functionality of the PI6 is available in the PI200 and PI4 interfaces

It is Renishaw's policy to support an obsolescent product, through repair, RBE, or replacement for 5 years and endeavour to support it for a further 5 years. This policy will be applied to the PI6.

The affected part number is A-1033-0001.

This product will be deleted from the next issue of the divisional price list but in the interim could you please manually delete it.

If you have any questions or comments on this bulletin please visit www.renishaw.com/cmmsupport and use the "Contact" facility. This will ensure that your call is logged and processed efficiently

Page 1 of 1 PBC1472