T +44 (0) 1453 524524 F +44 (0) 1453 524901 E UK@renishaw.com www.renishaw.com



## Renishaw CMM products division PRODUCT BULLETIN – PBC1777

Product:	SPAlite			Status:	Open	
Title:	SPAlite obsolescence		Date:	6/2/2015		
Distribution:		Internal	Subsidiari	es OEMs	Distributors	Retrofitters
Originator:						
Dave Joynson						
Reviewer:						
Andy Holding						
Summary:						
been superseded by the more advanced SPA3 amplifier. Therefore the SPAlite is now obsolete. Product bulletin PBC1766 contains more details on the SPA3 specification and part numbers. The bulletin can be accessed in the <a href="CMM support">CMM support</a> area of the Renishaw website.  Further details:  It is Renishaw's policy to support an obsolete product, through repair, RBE, or replacement for 5 years and will endeavour to support it for a further 5 years. This policy will be applied to the SPAlite.						
Actions:						
This product will be deleted from the next issue of the Renishaw CMM price list. Please also delete it from any other relevant price lists.						
Part numbers:						
The affected part numbers are :-						
A-5331-0010		S	SPAlite			
A-5331-0051		S	SPAlite			
A-5121-2002		L	JCC2-2 kit #2			
A-5518-1000		P	PH20 kit 1			

If you have any questions or comments on this bulletin please visit <a href="www.renishaw.com/cmmsupport">www.renishaw.com/cmmsupport</a> and use the "Contact" facility. This will ensure that your call is logged and processed efficiently.