Renishaw plc New Mills, Wotton-under-Edge, Gloucestershire GL12 8JR United Kingdom T +44 (0) 1453 524524 F +44 (0) 1453 524901 E UK@renishaw.com www.renishaw.com



## Renishaw CMM Products Division PRODUCT BULLETIN – PBC1567

Product:	PHC10-2 IEEE	Status:	Open
Title:	PHC10-2 IEEE obsolescence	Date:	1st December 2011

Originator:	Distribution:	
D joynson	Internal	✓
	Subsidiaries	✓
Reviewer:	OEMs	✓
B Gow	Distributors	✓
	Retrofitters	✓

## Summary:

The obsolescence notice PBC1474 for the PHC10-2 IEEE was issued late 2010 and the part number removed from the price list.

As detailed in PBC1474 the PHC10-2 IEEE was made obsolete from September 2011.

The affected part number is :- A-1368-0101 PHC10-2 IEEE

It is Renishaw's policy to support an obsolescent product, through repair, RBE, or replacement for 5 years and endeavour to support it for a further 5 years. This policy will be applied PHC10-2 IEEE.

If you have any questions or comments on this bulletin please visit <a href="www.renishaw.com/cmmsupport">www.renishaw.com/cmmsupport</a> and use the "Contact" facility. This will ensure that your call is logged and processed efficiently

Page 1 of 1 PBC1567