

# Renishaw CMM Products Division PRODUCT BULLETIN – PBC1589

Product:	REVO	Status:	Open
Title:	RCP2 and TDA release – open version	Date:	9 <sup>th</sup> February 2012


Originator:	Distribution:	
L Quick	Internal	✓
	Subsidiaries	✓
Reviewer:	OEMs	✓
B Gow	Distributors	✓
	Retrofitters	✓

# Summary:

We are pleased to announce that RCP2 and TDA are now available for use with REVO®.

## RCP2

The RCP2 is a narrower version of RCP thus increasing the capacity of our MRS rails.



The RCP has been made obsolete and if an RBE replacement is needed the RCP2 will be provided.

All RCP kit part numbers are still available to order but the contents will be changed to supply RCP2.

Page 1 of 2 PBC1589

### TDA

The TDA is a new addition to the REVO system that fits to the standard MRS system. It has been developed to allow the tip correct functionality developed for PH20 to be applied to REVO. To learn more about tip correct please use the following knowledgebase page link <a href="http://www.renishaw.com/cmmsupport/knowledgebase/en/17037.aspx">http://www.renishaw.com/cmmsupport/knowledgebase/en/17037.aspx</a>



### **Existing REVO kits**

The RCPs in the existing REVO kits will be replaced with RCP2 as standard.

The TDA will be added to all of the REVO kits as a standard offering and kit list prices will remain unchanged.

Part	Description	Kit Contents
number		
A-3060-0090	RCP2	RCP2 and fixing kit
A-3060-0085	TDA	TDA and fixing kit

# **Extended Warranty**

Renishaw's standard extended warranty package applies to the RCP2 as it is a serial numbered item.

### **Support policy**

The RCP2 is RBE only and is the same price as the RCP.

The TDA is replace at list price only product.

If you have any questions please contact the either the originator or the CMM product support team (01453 523444 or email: cmm.support@renishaw.com)

Page 2 of 2 PBC1589